



1. CLEAN ALL FIRESTONE PONDGARD SURFACES AS REQUIRED BY FIRESTONE SPECIFICATIONS.
2. TAKE EXTRA CARE TO CLEAN FACTORY SPLICES AND OTHER AREAS WHERE EXCESS DUSTING AGENT MAY HAVE ACCUMULATED.